



# Facilities Needs Report Brief

**Does your library have major capital needs that need to be addressed in the next 5 years?**



- 10/12 who checked “Window replacement (due to leaking or other functional reason)” also checked “Window replacement (e.g., UV glass)” as a response for facility resilience question. It seems likely those libraries will select windows that include climate resiliency factors, even if primary reason for replacement is function.

## Other, categorized



**Add Space**

- Create programming space for library
- Private study space
- Renovate section of lower level
- Build/retrofit small computer classroom
- Additional space
- Expansion
- Add makerspace and 3 quiet study areas

**Mechanical/Electrical/Plumbing Systems**

- Radiators (separate from HVAC)
- New mechanical and electrical
- Install French drains in lower level
- Fix/replace failed septic system
- Plumbing repairs/updates

**Exterior Work**

- Exterior refresh of walkways and patio
- Repointing of brickwork
- Siding replacement
- Roof drains
- Outer door repairs

**Parking Lot**

- Move handicap spots in parking lot
- Reseal the parking lot
- Parking lot improvements
- Driveway
- Expansion


**Structural Repair**

- Wall/ceiling repair due to water leak
- Mold remediation

**Miscellaneous Capital Needs**

- Reorganize library layout
- Heating envelope
- Replace furniture

## Has your library identified updates, modifications, or replacements that will increase the facility's resilience to extreme weather or impacts from climate change?



### Other

- New doors/entryways
- Insulate basement walls
- Roof drains
- Adaptations and mitigation in park operations/practice
- Replace insulation in attic of children's room

